INSPECTION REPORT (検品書)

SERIAL NUMBER(号機) : ZX30U-5A-32005	1915 HR
ENGINE NO.(エンジン号機) : 3TNV88-ZPHB-M4295	YR
EMISSION REGULATION(排ガス規制) : TIER 3 EMISSION STANDARDS 3次排ガス	EPA: WITH / (WITHOUT)

項目	評価	メモ	項目	評価	メモ
ENGINE エンジン			**UNDER CARRIAGE 足回り**		
Main Engine <エンジン本体>	C		Sprocket <スプロケット>	D	
Head Cover <ヘッドカバー>	C		Idler <アイドラー>	C	
Sound <音>	C		Shoe <シュー>	C	PAD=NEW 300 mm
Exhaust Pressure <排圧>	C		Link <リンク>	C	NO. Of Link 44
Exhaust Color <排気色>	C		Pin Bushing <ピンブッシュ>	D	
Muffler Body <マフラー本体>	C		Track Frame <トラックフレーム>	C	
Radiator <ラジエター>	C		TRACK & CARRIER ROLLER <下部＆上部ローラー>		F ① ✕②③④ ✕②③④ ① R
Oil Cooler <オイルクーラー>	C				
MAIN PUMP ポンプ			**OUT LOOKING 外観**		
Oil Leaking <オイル漏れ>	C		Boom <ブーム>	C	BOOM SWING ブームスウィング
Sound <音>	C		Arm <アーム>	C	
Power <パワー>	C		Bucket <バケット>	B	
Contol Valve <コントロールバルブ >	C		Bumper <バンパー>	C	
Hose/Pipe etc. <ホース/配管類>	C		Frame <フレーム>	C	
OPERATION SYSTEM 操縦関係			Tanks&Covers <タンク･カバー類>	C	
Running <走行>	C		Paint <塗装>	C	
Swing Motor <旋回モーター>	C		**HYD.CYLINDER シリンダー関係**		
Looseness of Swing Bearing (SIDE)<旋回横ガタ>	C		Boom Cylinder <ブームシリンダー>	C	
Looseness of Swing Bearing (UP/DOWN)<旋回縦ガタ>	C		Arm Cylinder <アームシリンダー>	C	
INTERIOR キャビン内装			Bucket Cylinder <バケットシリンダー>	C	
Cabin Appearance <キャビン外観>	C	CNP (ROPS)	**OTHER 付属部品**		
Glass <ガラス>					
Operator Seat <シート>	C	RIPPED 破れ	Blade <ブレード>	(WITH) / WITHOUT	
Floor Mat <フロアマット>	C	RIPPED 破れ	Arm Crane <アームクレーン>	WITH / (WITHOUT)	
Monitor <モニター>	C		Piping <配管>	WITH / (WITHOUT)	
Air-Cond. <エアコン>			Multi Control Lever <マルチコントロールレバー>	WITH / (WITHOUT)	
Operation Lever <操作レバー>	C		Lever Form <レバー方式>	(WRIST) / LONG	
Pedal <ペダル>	C		Battery <バッテリー>	(GOOD) / FLAT	

A : replaced with brand new or rebuilt parts B : in good working condition considering its age C : normal operation; appears worn and deterioration
D : operational, but need repairs E : need quick repairs or replacement parts
A : 新品または再生品 B : 経年に比例して良好 C : 稼働に異常は無いが経年相当の摩耗・劣化あり
D : 稼動はするが修理が必要 E : 即修理をしないと稼動しない

*We described this inspection report based on our judgement and view. We do not guarantee the condition shown on this inspection report.
*この検品書は私どもの見解判断に基づいて作成したものであり、機械の程度を保証するものではありません。